The Airbus Safety magazine

Under the Spotlights



Two recent events with damage to the passenger windows of the aircraft were reported to Airbus. Similar events also happened on non-Airbus aircraft. The damage was caused by the heat of spotlights used during promotional filming sessions. One of these events could have had serious safety consequences as damage was not detected on ground, and caused some window panes to detach from the aircraft during the next flight.

This article describes this event in more detail and how to prevent heat damage due to exterior lighting. It also recommends checking the condition of the aircraft before it returns to service.

Check the latest version of this article on <u>safetyfirst.airbus.com</u> and on the Safety first app for iOS and Android devices.





CASE STUDY

Event Description

An A321neo aircraft was performing a positioning flight before several sectors of operations. A limited number of people including some cabin crew members were on board. The aircraft was climbing toward its target altitude. At 10 000 ft, one of the cabin crew noticed an excessive amount of cabin noise and cold temperature while walking toward the empty middle part of the aircraft. He discovered that one of the windows on the left side of the cabin appeared to have slipped down from its usual position and that the window seal was flapping in the outside airflow (fig.1). He immediately informed the flight crew who decided to descend to 9 000 ft and to perform an in-flight turnback. The aircraft landed safely and without further incident.

When on the ground and with the aircraft parked, the flight crew performed an inspection of the aircraft exterior. They observed that two windows were missing and one was dislodged **(fig.2)**. Damage to the lower side of the left stabilizer, probably due to an impact of a departing part, was also noticed. Further inspection revealed that two additional windows were damaged on the left side of the fuselage and one window also showed signs of damage on the right side of the fuselage.





(fig.1) Picture of the window during the event (source: operator)

(fig.2) Picture of the damaged and missing windows after landing (source: investigation board)

Event Analysis

One day before the event, there was a filming session inside the aircraft, around the middle cabin area. There were 6 halogen (tungsten) lamphead spotlights, rated at 12 kW, placed outside the cabin windows to light the area being filmed. The 6 spotlights were first located on the right side of the aircraft at a distance between 6 to 9 meters from the fuselage, close to the overwing emergency exits, with the light beams focussed on the same area of fuselage **(fig.3)**. The lights were then moved to the left side of the aircraft for the second part of the filming session.



(fig.3) Lighting setup during the filming session (not to scale)





(fig.4) Picture of the filming session (source: operator)

Heat damage

The combined power of the 6 lamps in the halogen lighting setup was 72 kW. The exposure of the fuselage area to the spotlights lasted more than 4 hours on each side of the aircraft. The heat produced by the infrared radiation from the halogen spotlights damaged several cabin windows. This damage was not detected prior to the next flight.

The damage found on the affected windows during post-flight inspection included:

- Two window assemblies completely missing (one pane was retrieved on the runway)
- One window with missing outer pane
- Deformation of several other window panes
- Window seals in degraded condition
- Visible burn marks
- Melted foam ring at the interface between the window and the cabin lining.



(fig.5) Window protrusion due to deformation (left) and burn marks on the top of an outer pane (right) (source: investigation board)



CABIN WINDOWS

A cabin window assembly is typically composed of one inner and one outer pane made of **stretched acrylic** contained in a window seal **(fig.6)**. An additional transparent lining (not shown in the illustration) is present on the cabin side to protect the inner pane from impacts or scratches from the passenger side.



(fig.6) Typical structure of a cabin window

A plug-type structural element

The cabin window assembly is a **plug-type** structural component. In other words, it is positioned from the inside of the aircraft and **its size is bigger than the window frame** so that the differential pressure pushes it against the window frame. The window assembly is maintained in place by a retainer, which is attached to the window frame by bolts.

A fail-safe structural part

Each cabin window pane (i.e. both the inner and outer panes) are able to independently sustain the maximum cabin differential pressure usually experienced during a flight.

The outer pane sustains the loads. A small vent hole on the inner pane lets the cabin pressure into the space between the two panes. This prevents the inner pane from sustaining pressurization cycles on each flight. The inner pane is, therefore, not exposed to structural fatigue.

If the outer pane fails during a flight, the inner pane is designed to sustain the differential pressure loads and maintain the cabin pressure, which allows the continuation of the flight. The window assembly can then be replaced when the aircraft is back on the ground.

Risks associated with abnormal heat exposure

Shrink-back effect of acrylic

Cabin window panes are manufactured from a thick acrylic sheet that is heated to become softer, then stretched until the required thickness is reached. In normal operating temperature conditions, the acrylic remains in a stable state. However, if

excessive heat is applied to a stretched acrylic object, the acrylic softens and the object tends to shrink back to its original shape (fig.7).



Stable state in normal temperature conditions

Shrink-back effect under abnormally high temperature

(fig.7) Shrink-back effect of the stretched acrylic under abnormally high temperature

Risk of window pane ejection

If the passenger window panes are exposed to an excessive amount of heat, **the panes may start to shrink and could become smaller than the window frame.** If a damaged window is not detected before the aircraft returns to service, as in the event described earlier, there is a risk that the cabin pressure differential at altitude will force the affected window pane outwards, causing cabin air pressure leaks and eventually the ejection of the window pane (**fig.8**). If both the inner and outer panes are affected by the heat damage, the complete window assembly could fail and be ejected.



Normal condition of the window assembly in the window frame (no damage)



Excessive heat conditions may cause window panes to shrink

PREVENTING HEAT DAMAGE

When performing a filming session or photoshoot that requires the use of artificial lighting in close proximity to an aircraft, the following recommendations will prevent heat from the lights causing damage to the windows and fuselage.

Avoid using high thermal radiation lighting

Airbus recommends not to use high thermal radiation lighting devices, such as halogen (tungsten) or HMI lighting, during photoshoots or filming sessions outside or inside an aircraft. This type of lighting device emits a large amount of thermal energy. **Only use low energy lighting devices, such as LED lights,** which provide good lighting capabilities with low heat emission.

Limit exposure and regularly monitor the surface temperature

Switch off any lighting devices when not necessary to **limit the exposure time to the minimum**.

Even though Airbus aircraft materials have been qualified for use in elevated temperature environments, for example, taking into account operations or storage in

(fig.8) Risk of window pane ejection if the heat damage is not detected before the next flight



Cabin pressure may push the panes outwards if damage is not detected before the next flight



hot weather regions, Airbus recommendation is to make sure that the surface temperature of cabin and passenger windows, fuselage, interior equipment and all aircraft parts exposed to the lighting sources, **are monitored and do not exceed 55°C**.

Beware of the thermal radiation cumulative effect

Even if the minimum distance to the subject defined by the lighting device instructions is respected, when multiple lighting units are used at the same time, there is a thermal radiation cumulative effect that may cause overheating and damage to the aircraft.

For example, one halogen lighting unit located at the minimum recommended distance, and pointed at the fuselage may increase the surface temperature of the fuselage to 40°C (fig.9).

Using six similar halogen lighting devices simultaneously, which are located at the recommended minimum distance and all pointed at the fuselage, may quickly raise the surface temperature to 120°C due to the cumulation of the thermal radiation emitted from each light. This high temperature may cause damage to the object.

(fig.9) Thermal radiation cumulative effect



Thermal radiation cumulative effect

Check the aircraft for damage before return into service

After the filming session or photoshoot is finished, **Airbus recommends performing a visual inspection** of all cabin windows that were exposed to the lightning to check they are free of any damage or distortion before returning the aircraft to service.



Contributors:

Bruno ESTEBE

Thermal Analysis Expert Design Office

Jérôme GRAS

Cockpit and Cabin Windows Expert Design Office

Pierre LABRO

Accident/Incident Investigator Aviation Safety

Kamel NAIT ATIA

Nose and Fwd fuselage windows product leader Customer Support

Jens WIETING

Composite/hybrid structural design engineering Design Office

With thanks to Damien PARISE from Customer Support and Sylvain RAMADIER from the Flight and Integration Tests Centre photo lab The use of lighting devices during a filming session or photoshoot around an aircraft, or in the cabin, can have unintended consequences. High energy lighting devices can emit a level of thermal radiation that can damage the aircraft's fuselage, windows, or cabin interiors. This may even result in a failure in flight of the window assemblies due to the effects of the heat damage, leading to a loss of cabin pressure at altitude and potential injury to passengers or crew.

Several recommendations should be taken into consideration when planning a filming session or photo shoot involving any aircraft. These include only using low heat emitting lighting devices, such as LED lighting equipment, limiting the exposure of the fuselage, windows, or cabin interior to the lights, and regularly monitoring the surface temperature so that it does not exceed 55°C when exposed to the lights.

After the completion of the filming session, it is important to perform a thorough visual inspection of the areas that were exposed to the lighting to ensure there is no damage and that the aircraft is in a safe condition for its return to service.



Safety first, 2024. Safety first is published by Airbus S.A.S. 1, rond point Maurice Bellonte - 31707 Blagnac Cedex/France.

Editor: Yannick Malinge, Chief Product Safety Officer.

Editorial team: Guillaume Estragnat, Vanessa Sadi, Gwyneth Duggan, Javier Martinez Marina, Tim Roach.

Photos by Airbus.

© Airbus S.A.S. 2024 – All rights reserved. Proprietary documents.

By taking delivery of this Brochure (hereafter "Brochure"), you accept on behalf of your company to comply with the following guidelines:

• No other intellectual property rights are granted by the delivery of this Brochure than the right to read it, for the sole purpose of information.

• This Brochure and its content shall not be modified and its illustrations and photos shall not be reproduced without prior written consent of Airbus.

• This Brochure and the materials it contains shall not, in whole or in part, be sold, rented, or licensed to any third party subject to payment.

This Brochure contains sensitive information that is correct at the time of going to press.

This information involves a number of factors that could change over time, affecting the true public representation. Airbus assumes no obligation to update any information contained in this document or with respect to the information described herein.

Airbus S.A.S. shall assume no liability for any damage in connection with the use of this Brochure and of the materials it contains, even if Airbus S.A.S. has been advised of the likelihood of such damage.

Safety first

The Airbus Safety magazine

The Airbus magazine contributing to the enhancement of the safety of aircraft operations by increasing knowledge and communication on safety related topics.

Safety first is published by the Product Safety department. It is a source of specialist safety information for the use of airlines who fly and maintain Airbus aircraft. It is also distributed to other selected organizations and is available on digital devices.

Material for publication is obtained from multiple sources and includes selected information from the Airbus Flight Safety Confidential Reporting System, incident and accident investigation reports, system tests and fight tests. Material is also obtained from sources within the airline industry, studies and reports from government agencies and other aviation sources.

All articles in Safety first are presented for information only and are not intended to replace ICAO guidelines, standards or recommended practices, operator-mandated requirements or technical orders. The contents do not supersede any requirements mandated by the State of Registry of the Operator's aircraft or supersede or amend any Airbus type-specific AFM, AMM, FCOM, MMEL documentation or any other approved documentation.

Articles may be reprinted without permission, except where copyright source is indicated, but with acknowledgement to Airbus. Where Airbus is not the author, the contents of the article do not necessarily reflect the views of Airbus, nor do they indicate Company policy.

Contributions, comments and feedback are welcome. Enquiries related to this publication should be addressed to:

Airbus - Product Safety department (W)

1, rond point Maurice Bellonte 31707 Blagnac Cedex - France <u>safetycommunication@airbus.com</u>

Visit us at safetyfirst.airbus.com or install the Safety first app:

