



Avoiding Dual Bleed Loss



By: Patrick GRAVE
*Group Manager
Pneumatics, Ice and
Fire Protection Systems
Customer Services*



Christophe MATHE
*Engineer A320/A330/A340
Operational Standards
Customer Services*

1 | Introduction

Over the past years, the A320 family fleet experienced a significant number of dual air engine bleed losses. The consequences of these losses ranged from in-flight turn backs shortly after take-off, to full blown cabin depressurization events and flight diversions.

The aim of this article is to present the typical causes of the dual bleed losses and to explain how:

- The crew may mitigate the operational consequences of this type of occurrence by applying the pertinent procedures
- New maintenance and design improvements should reduce the number of such events in the future.

We are confident that the correct application of the above procedures and improvements should help airlines to limit occurrences of dual bleed loss incidents.

2 | Description of the pneumatic system

The main purpose of the dual bleed air system is to provide the air conditioning system with air regulated in both pressure and temperature. They also supply various air system consumers such as :

- Wing anti-ice protection
- Engine starter
- Hydraulic reservoir and water tank pressurization.




Figure 1: Pneumatic system layout

The bleed air system is installed in the nacelle and pylon of each engine and includes:

- For the pressure regulation:
 - An Intermediate Pressure Bleed Check Valve (IPCV)
 - A High Pressure Bleed Valve (HPV)
 - An Over Pressure Valve (OPV)
 - A Pressure Regulator Bleed Valve (PRV), which is commanded by a Temperature Limitation Thermostat (TLT). The TLT will order the PRV to reduce the pressure in the system in case of over-temperature.
- For the temperature regulation:
 - A precooler exchanger (PCE)
 - A Fan Air Valve (FAV), which is commanded by a Temperature Control Thermostat (TCT)
 - The TCT will order the FAV to increase air flow from the fan in case of over-temperature.
- For the system monitoring:
 - A Bleed Monitoring Computer (BMC).







Figure 2: Main components description

3 | Typical failure scenario

The dual bleed loss events usually happen when one bleed fails, resulting in the remaining bleed on the other engine to compensate for it.

The augmented flow of warm air from the engine core leads to a corresponding increase in the flow of cold air from the Fan to the Precooler.

In case of one engine bleed loss, the remaining bleed fails when the Fan Air Valve (FAV) does not let enough cold air reach the Precooler (PCE).

This causes the temperature downstream of the PCE to reach the 260°C (500°F) over-temperature threshold, which induces the automatic closure of the bleed system.

4 | Operational procedure to be applied

This excessive rise in temperature is caused mainly by either:

- Leakage of the TCT to FAV sense line
- TCT drift / failure
- Or FAV leakage / failure.

NOTE: In-service experience has shown that the root cause of over-temperature is often linked to a combination of the above factors.

Other possible causes are:

- Temperature sensor failure
- Wiring failure.

In the above scenario, the failure of the first bleed system leaves the second engine bleed to supply all the aircraft consumers. This bleed, in turn, is lost due to excessive demand.

After the failure of both bleed systems, the AIR DUAL BLEED FAULT paper procedure (QRH page 2.02 and FCOM 3.02.36 page 3) therefore recommends to initiate a rapid descent to FL200 and to reduce air demand, before attempting the recovery of the second bleed system.


Assuming that both PACKS are operative, the air demand is reduced by shutting OFF the PACK on the side of the first affected bleed system. The flight crew should then press twice the ENG BLEED pushbutton on the overhead panel associated to the second engine bleed, in order to reset it.

- DESCENT INITIATE
Descend rapidly to FL200 so that the bleed supply may be supplied by the APU, if the bleed system recovery is not successful.*
- **If both packs are available:**
If both packs are operative, it can be suspected that the second bleed system failed due to excessive demand. Recovery of the second failed engine bleed may be attempted.
 - **IF ENG 1 BLEED is lost first:**
 - PACK 1 OFF
 - ENGINE 2 BLEED. ON
 - **IF ENG 2 BLEED is lost first:**
 - PACK 2 OFF
 - ENGINE 1 BLEED. ON

* FL225 for APU Honeywell 131-9 (A)

Figure 3: Extract of Quick Reference Handbook page 2.02





The bleed should recover, and the flight should be able to resume to the destination airport with one engine bleed supplying one PACK (that automatically delivers high flow).

5 | Maintenance and design improvements

Following laboratory and flight tests, enhancements have been introduced in the domains of maintenance and design.

- Maintenance
 - Improved FAV leak check procedure in the Aircraft Maintenance Manual (AMM) (ref A)
 - Test of the engine bleed system performance. The AMM includes a new test of the capacity of the bleed system to function properly in a one bleed/two packs configuration (ref B)
 - Periodic cleaning of the TCT filter
As the clogging of the filter is considered to be a major contributor to the TCT temperature drift, a new mandatory MPD task has been introduced (ref C).

NOTE: The Aircraft Condition Monitoring System (ACMS) may be customized to monitor bleed temperature levels. This allows preventive troubleshooting to be performed before the bleed actually fails.

- Design
 - The TCT has been modified to react faster to excessive temperatures, thereby ordering the FAV to increase the cold air supply earlier than before (ref D)
 - In order to address the leakage issue, the FAV has been modified to include a seal between the actuator and actuator cover (ref E)
 - The pressure limitation function has been shifted. Even though the TLT function is not a root cause of bleed failure, it is considered to be an aggravating factor for an already degraded system (ref F)
 - New tooling is being developed to allow bleed air system health checks and to improve trouble shooting efficiency. These tools are expected to be available by the end of 2009.

6 | Conclusion

The root causes of the dual bleed loss scenario have been identified. Necessary prevention and design improvements have been put in place to address this issue.

Incorporation of the below enhancements should address the large majority of dual bleed loss occurrences. This will have a positive impact on our customer airlines' operations. We therefore highly recommend their timely application.

REFERENCES

- A) AMM task 36-11-54-720-001-01
- B) AMM task 36-11-00-710-003
- C) MPD Task 361143-01-1
- D) AIRBUS SB A320-36-1061 and LIEBHERR VSB 342-36-08
- E) LIEBHERR VSB 6730F-36-01 & 6730-36-03
- F) LIEBHERR VSB 341-36-06

Please consult the Retrofit Information Letter (ref. SEOT2 916.0468/08) issued in July 2008 for logistical advice on the completion of the A320 family dual bleed loss improvement action plan.



Safety First

The Airbus Safety Magazine
For the enhancement of safe flight through
increased knowledge and communications.

Safety First is published by the Flight Safety Department of Airbus. It is a source of specialist safety information for the restricted use of flight and ground crew members who fly and maintain Airbus aircraft. It is also distributed to other selected organisations.

Material for publication is obtained from multiple sources and includes selected information from the Airbus Flight Safety Confidential Reporting System, incident and accident investigation reports, system tests and flight tests. Material is also obtained from sources within the airline industry, studies and reports from government agencies and other aviation sources.

All articles in Safety First are presented for information only and are not intended to replace ICAO guidelines, standards or recommended practices, operator-

mandated requirements or technical orders. The contents do not supersede any requirements mandated by the State of Registry of the Operator's aircraft or supersede or amend any Airbus type-specific AFM, AMM, FCOM, MEL documentation or any other approved documentation.

Articles may be reprinted without permission, except where copyright source is indicated, but with acknowledgement to Airbus. Where Airbus is not the author, the contents of the article do not necessarily reflect the views of Airbus, neither do they indicate Company policy.

Contributions, comment and feedback are welcome. For technical reasons the editors may be required to make editorial changes to manuscripts, however every effort will be made to preserve the intended meaning of the original. Enquiries related to this publication should be addressed to:

Airbus

Product Safety department (GS)
1, rond point Maurice Bellonte
31707 Blagnac Cedex - France
Fax: +33(0)5 61 93 44 29
safetycommunication@airbus.com



Safety First
07 February 2009

Safety First is published
by Airbus S.A.S
1, rond point Maurice Bellonte
31707 Blagnac Cedex / France

Editor:
Yannick Malinge,
Vice President Flight Safety

Concept Design by
MULTI MEDIA SUPPORT 20090053

Computer Graphic by Quat'cou

Copyright: GSE 420 0046/09

Photos copyright Airbus
Photos by
ExM: Hervé Berenger, Philippe
Masclat, Hervé Goussé.
Photo copyright Germanwings

Computer rendering by ABAC

Printed in France by AMADIO

© Airbus S.A.S. 2009 – All rights reserved. Confidential and proprietary documents.

By taking delivery of this Brochure (hereafter "Brochure"), you accept on behalf of your company to comply with the following guidelines:

- > No other intellectual property rights are granted by the delivery of this Brochure than the right to read it, for the sole purpose of information.
- > This Brochure and its content shall not be modified and its illustrations and photos shall not be reproduced without prior written consent of Airbus.
- > This Brochure and the materials it contains shall not, in whole or in part, be sold, rented, or licensed to any third party subject to payment.

This Brochure contains sensitive information that is correct at the time of going to press. This information involves a number of factors that could change over time, effecting the true public representation. Airbus assumes no obligation to update any information contained in this document or with respect to the information described herein.

Airbus SAS shall assume no liability for any damage in connection with the use of this Brochure and of the materials it contains, even if Airbus SAS has been advised of the likelihood of such damages.