



# Do you know your ATC/TCAS panel ?



**By: Bernard VIGNAULT**

*Flight Operations Safety Enhancement Engineer*



## 1 | TCAS Fault leads to AIRPROX

Shortly after takeoff from London Heathrow, the ECAM alert TCAS FAULT was triggered in an Airbus A340-600. The ECAM procedure consists in setting the TCAS mode to standby. Unfortunately, the effects of the action were not the expected ones: the crew inadvertently switched off both transponder and TCAS instead of selecting the TCAS standby mode as per ECAM procedure. The Air Traffic Control secondary radar information was temporarily lost and prevented the automatic update of the flight data. In other words, the aircraft disappeared from the ATC radar screen and was not able to respond to other aircraft TCAS interrogation. During this time the Tower Traffic Controller tried to contact the approach centre. Although several attempts were made the calls were not answered. Unknown to the approach controller, the aircraft was climbing in conflict with another departing aircraft. As the aircraft transponder was not responding, no TCAS alerts nor Short Term Conflict Alert (in Air Traffic Control) triggered and the minimum separation reduced to 3.7 NM and 0 ft.

## 2 | TCAS controls

Let us have a closer look to the ECAM procedure and to the TCAS controls, to understand this scenario.

When the TCAS fails, the ECAM procedure indicates (on A340/330): TCAS MODE.....STBY (See fig 1).



*Fig 1: CAS FAULT ECAM procedure on A330/340*



Fig 2: Gables 40 ATC/TCAS control panel

The crew is expected to set the faulty system on standby.

In the above event, the airline had chosen for its fleet the TCAS panel, which is shown in figure 2.

On this panel, a single rotating selector enables the crew to switch between several modes, linked to ATC transponder and/or TCAS. When the selector is placed in **TA/RA** or **TA ONLY** positions, both TCAS and ATC

transponder operate. But if the selector is placed in one of the three other positions (**XPNDR**, **ALT RPTG OFF**, **STBY**), then the TCAS is on standby mode. In their intention to set the TCAS only on standby mode, as requested by the ECAM, the crew turned the selector until it reached the **STBY** position. **They did not immediately realize that this position set both the TCAS and the ATC transponder on standby mode.**



**TCAS + Transponder in standby**

**TCAS standby / Transponder On**

**TCAS + Transponder ON**

### 3 | Other TCAS Control Panels

Several types of panels are available to customers, and pilots have to pay attention to the switches layout when operating them, as functions may differ from a panel to another.

On Airbus basic TCAS panel, the controls are split into two parts:

- one side of the panel is dedicated to ATC transponder controls
- the other side is dedicated to TCAS control.




Fig 3: Basic ATC/TCAS control panel

Setting the TCAS mode to standby is done by setting the appropriate switch to the STBY position. The switch is easily identified, as it is located with other TCAS controls, and separated from ATC transponder controls (see fig 3).

When the TCAS switch is placed on the STBY position, the TCAS is electrically supplied but is inoperative, and the ATC transponder still operates normally. As a result, there will be no TCAS TA or RA on board the aircraft whose TCAS has been set to stand-by. However, the ATC transponder will be able to continue responding to potential intruder interrogation, and TA/RA information will continue to operate on-board the intruder.

Other designs exist for ATC/TCAS panel, on which TCAS setting on standby is achieved by setting the selector to XPNDR, STBY, ON or OFF, depending on which TCAS control panel is installed. On Gables 10 panel, for example, the selector should be turned from the normal TA/RA position to the ON position to set the TCAS on standby (see Figure 4). The ON legend is related to the ATC Transponder only. This is indicated by the fact that the ON legend is out of the settings related to the TCAS, that are gathered by a line associated to a TCAS label.




Fig 4: Gables 10 ATC/TCAS control panel – TCAS on standby




Fig 5: Gables 20 ATC/TCAS control panel – TCAS on standby

On Gables 20 panel, ATC transponder and TCAS have dedicated controls. TCAS is set on standby by placing the TCAS selector to the OFF position (see Figure 5).

## 4 | New ECAM procedure

**Setting the TCAS to standby mode can be achieved by setting the selector to XPNDR, STBY, ON or OFF, depending on which TCAS control panel is installed.**

The Flight Warning Computer that generates the ECAM procedure in case of a TCAS fault has no means of determining what type of ATC/TCAS control panel is installed. It is therefore not possible to provide the crew with a customized ECAM procedure indicating the setting to be reached for each panel.

This is why the TCAS FAULT ECAM procedure is generic and provides the objective of the action to be performed: TCAS MODE.....STBY. It is then up to the crew to place the right selector in the right position.

### ECAM Change

Setting the TCAS on stand-by when it is faulty enables to remove the TCAS FAULT flags on PFD and ND.

But the related in-service event highlighted the difficulty for the crew to use the right setting when the word “STBY” is displayed on the ECAM with a panel that differs from the AIRBUS standard one. Airbus then decided to remove the action line TCAS MODE.....STBY from the ECAM procedure and to accept the drawback of the flags remaining on PFD and ND after the failure. This modification will be effective upon fitting with new FWC standards. This modification is only applicable to Long Range aircraft, as the TCAS FAULT procedure is crew awareness only (no action line) on Single Aisle and A380 aircraft, and there is no ECAM warning for TCAS failure on A300/A310 family.

In the interim period before FWC standards are installed, AIRBUS published an OEB to inform crews not to apply the action line TCAS MODE.....STBY, in the case of a TCAS FAULT ECAM caution. The TCAS FAULT ECAM caution should be considered as a “crew awareness”.

This information was dispatched to airlines through FOT 999.0138/06 on 11<sup>th</sup> December 2006. The crews are informed of the deviation from ECAM procedure by:

- OEB **68/1** for **A330** aircraft (cancelled by FWC STD 2)
- OEB **82/1** for **A340** aircraft (cancelled by FWC STD L11 for A340-200/300 aircraft and FWC STD T2 for A340-500/600 aircraft)



# Safety First

The Airbus Safety Magazine  
For the enhancement of safe flight through  
increased knowledge and communications.

Safety First is published by the Flight Safety Department of Airbus. It is a source of specialist safety information for the restricted use of flight and ground crew members who fly and maintain Airbus aircraft. It is also distributed to other selected organisations.

Material for publication is obtained from multiple sources and includes selected information from the Airbus Flight Safety Confidential Reporting System, incident and accident investigation reports, system tests and flight tests. Material is also obtained from sources within the airline industry, studies and reports from government agencies and other aviation sources.


All articles in Safety First are presented for information only and are not intended to replace ICAO guidelines, standards or recommended practices, operator-mandated

requirements or technical orders. The contents do not supersede any requirements mandated by the State of Registry of the Operator's aircraft or supersede or amend any Airbus type-specific AFM, AMM, FCOM, MEL documentation or any other approved documentation.

Articles may be reprinted without permission, except where copyright source is indicated, but with acknowledgement to Airbus. Where Airbus is not the author, the contents of the article do not necessarily reflect the views of Airbus, neither do they indicate Company policy.

Contributions, comment and feedback are welcome. For technical reasons the editors may be required to make editorial changes to manuscripts, however every effort will be made to preserve the intended meaning of the original. Enquiries related to this publication should be addressed to:

**Airbus**  
Product Safety department (GS)  
1, rond point Maurice Bellonte  
31707 Blagnac Cedex - France  
Fax: +33(0)5 61 93 44 29  
[safetycommunication@airbus.com](mailto:safetycommunication@airbus.com)



**Safety First**  
# 04 June 2007

**Safety First is published  
by Airbus S.A.S**  
1, rond point Maurice Bellonte  
31707 Blagnac Cedex / France

**Editors:**  
Yannick Malinge,  
**Vice President Flight Safety**  
Christopher Courtenay,  
**Director of Flight Safety**

**Concept Design** by  
HCSGM 20070592  
**Production** by Quat'cou

**Copyright:** GSE

Photos copyright Airbus  
Photos by ExM:  
Hervé Berenger  
Philippe Masclet  
Hervé Goussé

**Printed in France**

© Airbus S.A.S. 2007 – All rights reserved. Confidential and proprietary documents.

By taking delivery of this Brochure (hereafter "Brochure"), you accept on behalf of your company to comply with the following guidelines:

- ⑦ No other intellectual property rights are granted by the delivery of this Brochure than the right to read it, for the sole purpose of information.
- ⑦ This Brochure and its content shall not be modified and its illustrations and photos shall not be reproduced without prior written consent of Airbus.
- ⑦ This Brochure and the materials it contains shall not, in whole or in part, be sold, rented, or licensed to any third party subject to payment.

This Brochure contains sensitive information that is correct at the time of going to press. This information involves a number of factors that could change over time, effecting the true public representation. Airbus assumes no obligation to update any information contained in this document or with respect to the information described herein.

Airbus SAS shall assume no liability for any damage in connection with the use of this Brochure and of the materials it contains, even if Airbus SAS has been advised of the likelihood of such damages.